



Quantitative Measurement of Photo-luminescent Materials.

Project Plan


By: John Tomes (jtt10@aber.ac.uk)

Abstract:

A Gantt chart showing key objectives and time schedule. A Workshop Gantt chart showing an agreed production schedule. A Bubble diagram is included to show key features for consideration and investigation.

Quantitative Measurement of Photo-Luminescent Materials.

Gantt chart for Project Time Plan.



Workshop Manufacturing Plan

Initial sketches and CAD models have now been show to the workshop (Matt Gunn and David Lewis) and the manufacturing estimates shown below have been agreed in principal, subject to testing and development.

